

22-30 CALIBER DECAP/FLARE



Attributes

- Name: LEE PRECISION 22-30 CALIBER DECAP/FLARE
- Manufacturer: LEE PRECISION
- Product no.: 100040902
- Mfr. No.: 91587
- Delivery weight: 0.018kg
- Shipping height: 13mm
- Shipping width: 51mm
- Shipping length: 127mm
- UPC: 734307915872

Item details

Made in USA

Table of Contents

- [Startpage](#)
- [English: Safety Instruction Guide for LEE PRECISION 2230 Caliber DECAP/FLARE](#)
- [Français: Guide de Sécurité pour le DECAP/FLARE LEE PRECISION 2230 CALIBER DECAP/FLARE](#)

Safety Instruction Guide for LEE PRECISION 2230 Caliber DECAP/FLARE

Introduction

Thank you for choosing the LEE PRECISION 2230 Caliber DECAP/FLARE. This product is designed to enhance your reloading experience by improving efficiency and accuracy. To ensure your safety and the proper functioning of this tool, please read and follow the safety instructions outlined in this guide.

General Safety Guidelines

- Ensure that you are familiar with the safe handling and operation of reloading equipment.
- Always wear appropriate personal protective equipment (PPE) such as safety glasses and gloves when using this product.
- Keep the product out of reach of children and vulnerable individuals.
- Regularly inspect the DECAP/FLARE for any signs of wear or damage before each use.
- Do not use the product for any purpose other than its intended use.
- Report any unsafe conditions or accidents to the relevant authorities.

Specific Safety Precautions for Use

- Always work in a wellventilated area when using reloading tools.
- Do not exceed the specified caliber compatibility of 2230 when using this product.
- Ensure that the Swage Decapping Die is properly secured before using the DECAP/FLARE punch.
- Avoid applying excessive force when using the punch to prevent injury or damage.
- If you experience any unusual resistance, stop using the product immediately and inspect for issues.

Instructions for Installation and Usage

Installation

1. Ensure that the Swage Decapping Die is clean and free of debris.
2. Insert the DECAP/FLARE punch into the designated slot of the Swage Decapping Die.
3. Secure the punch in place according to the manufacturer's instructions.

Usage

1. Prepare your reloading setup according to standard practices.
2. Align the case with the DECAP/FLARE punch.
3. Apply steady pressure to the handle to decap and flare the case.
4. Inspect the decapped case for any defects or irregularities after use.
5. Store the DECAP/FLARE punch in a safe and dry location when not in use.

Disposal Instructions

- Dispose of the DECAP/FLARE punch according to local regulations for metal waste.
- Do not dispose of the product in regular household waste.
- Consider recycling options where available.

Contact Information for Further Support

For any questions or concerns regarding the use of the LEE PRECISION 2230 Caliber DECAP/FLARE, please consult the manufacturer's website or contact their customer support.

By following these safety instructions, you can ensure a safe and effective reloading experience with the LEE PRECISION 2230 Caliber DECAP/FLARE. Thank you for your attention to safety.

Guide de Sécurité pour le DECAP/FLARE LEE PRECISION 2230 CALIBER DECAP/FLARE

Introduction

Merci d'avoir choisi le DECAP/FLARE LEE PRECISION 2230 CALIBER DECAP/FLARE. Ce produit est conçu pour la décalage et le décalage de cartouches. Pour garantir une utilisation sûre et efficace, veuillez lire attentivement ce guide de sécurité.

Lignes Directrices Générales de Sécurité

- Assurez-vous que le produit est utilisé uniquement pour son usage prévu.
- Vérifiez régulièrement le produit pour détecter tout signe d'usure ou de dommage.
- Conservez le produit hors de portée des enfants.
- Ne pas utiliser le produit si vous n'êtes pas sûr de son état ou de son fonctionnement.
- En cas de doute, consultez un professionnel avant utilisation.

Précautions de Sécurité Spécifiques à l'Utilisation

- Toujours porter des lunettes de sécurité lors de l'utilisation pour protéger vos yeux.
- Ne pas toucher les parties mobiles pendant le fonctionnement.
- Gardez vos mains et votre visage éloignés des zones de travail pendant l'utilisation.
- Ne pas forcer l'outil ; si vous rencontrez une résistance, arrêtez-vous et vérifiez le produit.
- Ne pas utiliser le produit dans des environnements humides ou mouillés.

Instructions pour l'Installation et l'Utilisation

1. Installation du produit :

- Retirez le DECAP/FLARE de son emballage.
- Assurez-vous que le produit est propre et exempt de débris.
- Installez le DECAP/FLARE dans votre presse à recharger selon les instructions du fabricant de la presse.
- Vérifiez que le DECAP/FLARE est bien fixé avant de commencer à l'utiliser.

2. Utilisation du produit :

- Placez la cartouche dans la presse à recharger.
- Actionnez la presse pour décaler la cartouche.
- Vérifiez que le décalage est complet et que la cartouche est en bon état avant de poursuivre.
- Nettoyez le DECAP/FLARE après utilisation pour maintenir ses performances.

Instructions de Mise au Rebut

- Ne jetez pas le produit avec les déchets ménagers.
- Suivez les réglementations locales pour le recyclage ou l'élimination des outils.
- Si le produit est endommagé ou hors d'usage, contactez un centre de recyclage local pour des conseils sur l'élimination.

Informations de Contact pour un Support Supplémentaire

Pour des questions de sécurité ou des préoccupations concernant ce produit, veuillez contacter le point de

contact local de l'UE. Assurezvous d'avoir le numéro de modèle et les détails de votre achat à portée de main pour faciliter la communication.

Merci de respecter ces directives pour garantir votre sécurité et celle des autres lors de l'utilisation du DECAP/FLARE LEE PRECISION 2230 CALIBER DECAP/FLARE.